

Unit	Purchased	Model	Description	KM's
673	1/10/2003	HZJ105	Landcruiser Station Wagon VIN JTECB09J703013972	184808

**Current condition**

Was used as a shift change vehicle on the mine  
 Has had some rust removed, slight panel damage  
 Recovery points, slight noise coming from 3rd diff

**Recent Maintenance History**

W/O No.	Finish Date	Plant Item	Work Description	Actual Cost
10050486	28-Apr-10	4CI-VEH673	673 Light Vehicle Service	134.54
037573	8-Sep-10	4CI-VEH673	5000 km Service completed	465.69
047564	11-Feb-11	4CI-VEH673	40000 km Service completed	1019.32
043078	2-Mar-11	4CI-VEH673	Passenger side headlight not working completed	200.46
055325	29-Apr-11	4CI-VEH673	5000 km Service by Blair29/4/10 @ 128217km	707.54
060497	29-Jun-11	4CI-VEH673	5000 km Service completed	665.33
035750	9-Aug-11	4CI-VEH673	Replaced gas struts under bonnet	830.84
064687	5-Sep-11	4CI-VEH673	5000 km Service Completed@137685kms	506.32
067903	17-Oct-11	4CI-VEH673	20000 km Service	913.45
072629	8-Dec-11	4CI-VEH673	5000 km Service 147511kms	394.12
077343	18-Jan-12	4CI-VEH673	Front Left Tyre, Drag link rubber, Timing Light on	267.77
077307	2-Feb-12	4CI-VEH673	5000 km Service completed	907.59
093019	19-Mar-12	4CI-VEH673	bullbar on vehicle has been damaged and Drivers	147
090694	19-Mar-12	4CI-VEH673	5000 km Service Completed	435.58
098100	11-May-12	4CI-VEH673	40000 km Service Completed	1734.46
103742	12-Jul-12	4CI-VEH673	5000 km Service Completed	509.13
111341	10-Sep-12	4CI-VEH673	5000 km Service Completed	446.12
114594	25-Oct-12	4CI-VEH673	Power steering pump leaking	943.67
114595	29-Oct-12	4CI-VEH673	seatbelt warning light on dash remains on	1430.5
114708	2-Nov-12	4CI-VEH673	Left side Fender rusted out and steering wheel	1653.8
115848	21-Nov-12	4CI-VEH673	5000 km Service Completed @ 177,304km	509.12
120373	18-Jan-13	4CI-VEH673	20000 km Service Completed @ 182,099 km	583.21