

Unit	Purchased	Model	Description	KM's
649	1/06/2000	HZJ79	Landcruiser manual utility VIN JTELB71JX007760	198099
Recent Maintenance History				
W/O No.	Finish Date	Plant Item	Work Description	Actual Cost
028302	10-Jun-10	4CI-VEH649	649 5000 km Service completed	441
031233	10-Jun-10	4CI-VEH649	649 replace clutch completed	1308
038433	1-Nov-10	4CI-VEH649	40000 km Service completed	1735.41
048612	31-Jan-11	4CI-VEH649	Brakes making noise xcompleted	962.15
047559	7-Feb-11	4CI-VEH649	5000 km Service completed	194.87
058047	13-May-11	4CI-VEH649	replace cracked front diff housing pt no 43110-60310	2360.42
056414	24-May-11	4CI-VEH649	Panard rod rubbers worn. completed	220.5
057514	24-May-11	4CI-VEH649	Hand brake light stays on, Handbrake U/S completed	588
055829	24-May-11	4CI-VEH649	5000 km Service completed	2673.62
060593	24-Jun-11	4CI-VEH649	Very noisy rattle when driving. Noise not there	1386.5
065735	16-Sep-11	4CI-VEH649	5000 km ServiceCOMPLETED@176172kms	1497
066363	30-Sep-11	4CI-VEH649	Remove crane and fit to new land cruiser	4099
089175	10-Feb-12	4CI-VEH649	hand brake not holding	220.5
092199	16-Mar-12	4CI-VEH649	20000 km Service Completed	782.08
098128	5-May-12	4CI-VEH649	seat cover U/S	626.4
102441	21-Jun-12	4CI-VEH649	5000 km Service Done by Blair21/6/12 @ 186296 km	677.07
104712	4-Sep-12	4CI-VEH649	Repair Drivers side seat	552.64
101103	4-Sep-12	4CI-VEH649	Right side Head light low beam not working.	690.41
099591	4-Sep-12	4CI-VEH649	wipers not working	797.42
093985	4-Sep-12	4CI-VEH649	Left side rear wheel came off the vehicle studs	1841.68
089788	4-Sep-12	4CI-VEH649	Unit 649 needs a flood light fitted to the top of	1908.04
111346	26-Sep-12	4CI-VEH649	5000 km Service Completed	952.29
114045	5-Oct-12	4CI-VEH649	FIT DUAL BATTERY SYSTEM, 7-9-12,COMPLETE	2013.65
122318	4-Feb-13	4CI-VEH649	5000 km Service completed @ 195681	627.96
125160	5-Feb-13	4CI-VEH649	please replace vehicle battery. completed	243.5
127098	11-Apr-13	4CI-VEH649	Vehicle #649 Motor Keeps Cutting out Fuel Problem	183.75
127292	15-Apr-13	4CI-VEH649	running rough under load & blowing blue smoke	257.25

