

| Unit | Purchased | Model | Description                                      | KM's   |
|------|-----------|-------|--|--------|
| 645  | 1/10/1999 | HZJ79 | Landcruiser manual utility VIN JTELB71JX07001327 | 201430 |

**Current condition**

Stuck in 2nd gear  
 Low power. Hard to start  
 Rust in tray. Body rough.

**Recent Maintenance History**

| W/O No.  | Finish Date | Plant Item | Work Description                                 | Actual Cost |
|----------|-------------|------------|--|-------------|
| 068140   | 6-Dec-11    | 4CI-VEH645 | Fuel pump not working                            | 0           |
| 070188   | 4-Nov-11    | 4CI-VEH645 | 40000 km Service completed@ 200425kms            | 1204.7      |
| 067438   | 23-Sep-11   | 4CI-VEH645 | One head light out Completed                     | 388.5       |
| 062208   | 15-Jul-11   | 4CI-VEH645 | Slight wheel wobble need fuel pump looked at     | 0           |
| 056413   | 28-Jun-11   | 4CI-VEH645 | Panard rod rubbers worn                          | 323.16      |
| 059616   | 16-Jun-11   | 4CI-VEH645 | Steering low                                     | 0           |
| 059446   | 16-Jun-11   | 4CI-VEH645 | 5000 km Service completed                        | 687.19      |
| 054253   | 23-May-11   | 4CI-VEH645 | panel damage to drivers door, windscreen cracked | 330         |
| 051912   | 4-Apr-11    | 4CI-VEH645 | 5000 km Service completed                        | 839.07      |
| 054254   | 4-Apr-11    | 4CI-VEH645 | front tank fuel guage not working correctly      | 0           |
| 050112   | 1-Apr-11    | 4CI-VEH645 | repair chipped windscreen                        | 330         |
| 030111   | 23-Jul-10   | 4CI-VEH645 | 645 20000 km Service completed                   | 543.2       |
| 031516   | 17-Jun-10   | 4CI-VEH645 | repair stock 10626                               | 2240        |
| 027666   | 1-Jun-10    | 4CI-VEH645 | 645 bad gearbox noise developing completed       | 1016.22     |
| 030222   | 1-Jun-10    | 4CI-VEH645 | 645 5000 km Service completed                    | 441         |
| 027725   | 19-Apr-10   | 4CI-VEH645 | 645 replace windscreen                           | 375         |
| 10049514 | 7-Apr-10    | 4CI-VEH645 | 645 Light Vehicle Service. no show 19.2          | 229.1       |
|          |             |            |  |             |