

Unit	Purchased	Model	Description	KM's
672	4/01/2003	HZJ79	Landcruiser manual utility VIN JTELB71J207035195	189499

Current condition

Low power.

Body fair.

Recent Maintenance History				
W/O No.	Finish Date	Plant Item	Work Description	Actual Cost
067633	8-Feb-12	4CI-VEH672	replace rear shockies. Checked rear shockies ok	186.22
076382	8-Feb-12	4CI-VEH672	Follow up on previous problems with motor	73.5
077918	8-Feb-12	4CI-VEH672	5000 km Service Completed	1587.72
077427	17-Jan-12	4CI-VEH672	Top of radiator burst/inspection of motor after	1799.87
074770	14-Dec-11	4CI-VEH672	please adjust/repair handbrake.185330kms completed	331.34
066349	13-Dec-11	4CI-VEH672	replace r/h seat 185330kms completed	681.45
070191	13-Dec-11	4CI-VEH672	5000 km Service 185330kms completed	470.83
068501	12-Dec-11	4CI-VEH672	please adjust/repair handbrake ,repair	463.92
072906	18-Nov-11	4CI-VEH672	Exhaust Gasket failure,please repair as soon as	332
070940	10-Nov-11	4CI-VEH672	Daily topup of powersteering fluid.No high beam.	0
067431	31-Oct-11	4CI-VEH672	20000 km Service completed by Blair 31/10/11@ 180845 Km	1087.35
069084	20-Oct-11	4CI-VEH672	Power steering pump not working	0
063485	14-Oct-11	4CI-VEH672	Please fit spotlights to bullbar and floodlights	0
066905	12-Oct-11	4CI-VEH672	Motor missing and blows smoke.	627
064788	19-Sep-11	4CI-VEH672	Passenger side door hard to open. completed by Paul 6/9/11.	144
066884	16-Sep-11	4CI-VEH672	handbrake adjustment needed. completed by blair 6/9/11	992
060501	13-Aug-11	4CI-VEH672	5000 km Service completed by Blair 13/8/11@171391 km	295.25
061515	12-Aug-11	4CI-VEH672	5000 km Service& rear brakes comp by Blair 12/8/11@ 171391km	743
053259	3-Aug-11	4CI-VEH672	AM/FM radio aerial U/S please replace	0
057910	29-Jun-11	4CI-VEH672	40000 km Service completed by Blair 29/6/11 @ 164754	1837.68
061027	29-Jun-11	4CI-VEH672	Front CV's replaced by blair29/6/11 @ 164754km	1159

039215	23-May-11	4CI-VEH672	Speedometer U/S repaired speedo	0
058512	23-May-11	4CI-VEH672	Please adjust handbrake completed	220.5
056759	4-May-11	4CI-VEH672	5000 km Service extra 4/5/11 completed	632.76
057211	3-May-11	4CI-VEH672	brake repairs by Blair 3/5/10 @ 155729km	471
055849	29-Apr-11	4CI-VEH672	Adjust Handbrake.T belt on.Handbrake completed	560.64
054115	12-Apr-11	4CI-VEH672	5000 km Service completed	639.82
048007	14-Mar-11	4CI-VEH672	Please adjust or repair handbrake. completed	1666.12
043887	14-Mar-11	4CI-VEH672	5000 km Service completed	1441.86
049104	18-Feb-11	4CI-VEH672	Wiper washer pump U/S.	0
048008	9-Feb-11	4CI-VEH672	Please adjust headlights.	0
042503	8-Dec-10	4CI-VEH672	repair stock 10626 GBX	2970
045820	3-Dec-10	4CI-VEH672	Please replace two radio. playing up.	880
043997	30-Nov-10	4CI-VEH672	Please replace drivers side seat.	0
042425	1-Nov-10	4CI-VEH672	Gearbox U/S,all gears.Will require carrier truck.	322.64
042430	1-Nov-10	4CI-VEH672	Reverse light U/S	0
041653	28-Oct-10	4CI-VEH672	motor belts please replace.	0
042017	19-Oct-10	4CI-VEH672	Please repair leaking rear brakes and adjust completed	1091.95
034496	1-Sep-10	4CI-VEH672	Drivers seat repair/replace checked ok	73.5
035985	1-Sep-10	4CI-VEH672	Drivers seat ,dropped on one side please ok	73.5
036567	1-Sep-10	4CI-VEH672	40000 km Service completed	1460.96
036741	13-Aug-10	4CI-VEH672	Drivers door difficult to open.completed	73.5
033450	22-Jul-10	4CI-VEH672	5000 km Service completed	873
030739	24-Jun-10	4CI-VEH672	672 5000 km Service completed	723.07
033002	24-Jun-10	4CI-VEH672	Drivers side front park light U/S completed	73.5
031494	17-Jun-10	4CI-VEH672	Repair of stock 10626 GBX	3941
028426	10-Jun-10	4CI-VEH672	672 5000 km Service	0
025770	29-May-10	4CI-VEH672	672 Grinding Noise in thow out bearing completed	1024.36
030976	29-May-10	4CI-VEH672	672 bad knocking when in reverse, gearbox may completed	588
20021041	5-May-10	4CI-VEH672	672 Repairs to hiab completed	1325
026631	5-May-10	4CI-VEH672	672 5000 km Service completed	473.64
027341	5-May-10	4CI-VEH672	672 LH Front hub seal leak completed	0
027518	5-May-10	4CI-VEH672	672 High beam u/s. Window winder completed	0

026464	5-May-10	4CI-VEH672	672 fit full set of seat covers. completed	175
026459	29-Apr-10	4CI-VEH672	672 Hand Brake requires adjustment.completed	0
028321	9-Apr-10	4CI-VEH672	672 20000 km Service	0